



CUSTOMER OPERATIONS  
 160 RIO ROBLES  
 SAN JOSE, CA 95134

PDN #: M000776

DATE: 04-Apr-14

## PRODUCT DISCONTINUANCE NOTICE

| Notice Type    | Maxim Part Number | Recommended Replacement | Last Order Date | Last Delivery Date | Reason   |
|----------------|-------------------|-------------------------|-----------------|--------------------|--|
| Discontinuance | MAX9177EUB+       | MAX9176EUB+             | 4-Oct-2014      | 3-Apr-2016         | Part can no longer be manufactured                 |
| Discontinuance | MAX9177EUB+T      | MAX9176EUB+T            | 4-Oct-2014      | 3-Apr-2016         | Part can no longer be manufactured                 |
| Discontinuance | MAX3600CTL+       | MAX3600ACTL+            | 4-Apr-2014      | 3-Apr-2016         | Part can no longer be manufactured                 |
| Discontinuance | MAX3600CTL+TC1M   | MAX3600ACTL+T           | 4-Oct-2014      | 3-Apr-2016         | Part can no longer be manufactured                 |
| Discontinuance | MAX3600EVKIT#W    | MAX3600EVKIT#           | 4-Apr-2014      | 3-Apr-2016         | The eval kit is no longer supported                |
| Discontinuance | MAX9316AEWP       | MAX9315EUP+             | 4-Oct-2014      | 3-Apr-2016         | Part is leaded, and a lead-free replacement exists |
| Discontinuance | MAX15301ETJ+      | MAX15301AA01+CK         | 4-Oct-2014      | 3-Apr-2016         | The part was not released                          |
| Discontinuance | MAX15301ETJ+T     | MAX15301AA01+TCK        | 4-Oct-2014      | 3-Apr-2016         | The part was not released                          |
| Discontinuance | MAX9123ESE        | MAX9123EUE+             | 4-Oct-2014      | 3-Apr-2016         | Part is leaded, and a lead-free replacement exists |
| Discontinuance | MAX3989ETG+       | N/A                     | 4-Apr-2014      | 3-Apr-2016         | The part was not released                          |
| Discontinuance | 806-0494-20+D     | N/A                     | 4-Oct-2014      | 3-Apr-2016         | Part can no longer be manufactured                 |
| Discontinuance | MAX9402EHJ        | MAX9406ETJ+             | 4-Oct-2014      | 3-Apr-2016         | Part is leaded, and a lead-free replacement exists |
| Discontinuance | DS2404B+          | DS2417P+                | 4-Oct-2014      | 3-Apr-2016         | Part can no longer be manufactured                 |
| Discontinuance | DS2404B+T&R       | DS2417P+T&R             | 4-Oct-2014      | 3-Apr-2016         | Part can no longer be manufactured                 |
| Discontinuance | DS2404S-001+      | DS2417P+                | 4-Oct-2014      | 3-Apr-2016         | Part can no longer be manufactured                 |
| Discontinuance | DS2404S-001+T&R   | DS2417P+T&R             | 4-Oct-2014      | 3-Apr-2016         | Part can no longer be manufactured                 |
| Discontinuance | MAX9729ETI+T      | MAX97220AETE+T          | 4-Oct-2014      | 3-Apr-2016         | Part can no longer be manufactured                 |
| Discontinuance | MAX9729ETI+       | MAX97220AETE+           | 4-Oct-2014      | 3-Apr-2016         | Part can no longer be manufactured                 |
| Discontinuance | MAX9729EVCMAXQU+  | MAX97220AEVKIT+         | 4-Apr-2014      | 3-Apr-2016         | Part can no longer be manufactured                 |
| Discontinuance | MAX9729EVKIT+     | MAX97220AEVKIT+         | 4-Apr-2014      | 3-Apr-2016         | Part can no longer be manufactured                 |
| Discontinuance | MAX3601CEVSY#-W   | MAX3601CEVSY#           | 4-Apr-2014      | 3-Apr-2016         | The eval kit is no longer supported                |
| Discontinuance | MAX15108EVKIT#    | MAX15108AEVKIT#         | 4-Apr-2014      | 3-Apr-2016         | Part can no longer be manufactured                 |
| Discontinuance | MAX15108EWP+      | MAX15108AEWP+           | 4-Oct-2014      | 3-Apr-2016         | Part can no longer be manufactured                 |
| Discontinuance | MAX15108EWP+T     | MAX15108AEWP+T          | 4-Oct-2014      | 3-Apr-2016         | Part can no longer be manufactured                 |
| Discontinuance | MAX86900EFD+      | MAX86900AEFD+           | 4-Apr-2014      | 3-Apr-2016         | The part was not released                          |
| Discontinuance | MAX86900EFD+T     | MAX86900AEFD+T          | 4-Apr-2014      | 3-Apr-2016         | The part was not released                          |
| Discontinuance | MAX9179EUE+       | N/A                     | 4-Oct-2014      | 3-Apr-2016         | Part can no longer be manufactured                 |
| Discontinuance | DS2502X1          | DS2502R+T&R             | 4-Oct-2014      | 3-Apr-2016         | Part can no longer be manufactured                 |
| Discontinuance | DS2502X1#U        | DS2502R+T&R             | 4-Oct-2014      | 3-Apr-2016         | Part can no longer be manufactured                 |

